Reset

To reset the scanner and apply parameters from the configuration file, scan the following bar code.

Reset

Reset Factory Defaults

To reset the scanner to factory defaults, scan the following bar code. This rebuilds the configuration file from program memory.

Reset Factory Defaults

Set Date and Time

> **NOTE** You must scan the configuration bar codes to set the time and date stamp on the scanner. The time and date can not be set or edited in the **config.ini** file. This setting persists for three months if the scanner is not used.

Set Date

Scan the **Set Date** bar code, then scan six numeric digits in the format **mmddyy** from *Numeric Bar Codes for Date and Time Settings on page 3-6* (first two for the month, second two for the day, third two for the year).

> **NOTE** To change the date format from **mmddyy**, see *DateFormat on page 1-23*.

Set Date

Set Time

Scan the **Set Time** bar code, then scan four numeric digits in the format **hhmm** from *Numeric Bar Codes for Date and Time Settings on page 3-6* representing the time according to the 24 hour clock (first two for the hour, second two for the minute).

For example, to set the time to 8:45 in the morning, scan the following bar code, then scan 0, 8, 4, 5. To set the time to 3:07 in the afternoon, scan 1, 5, 0, 7.

> **NOTE** To change the time format between **12h** and **24h**, see *TimeFormat on page 1-23*.

Set Time

Cancel Date and Time Setting

Scan the **Cancel Set Date/Time** bar code to cancel the date and time settings.

Cancel Set Date/Time

Numeric Bar Codes for Date and Time Settings

||||| |||||
0

||| ||||| |
1

||| ||||| |
2

||| ||||| |
3

||| ||||| |
4

||| ||||| |
5

||| ||||| |
6

||| ||||| |
7

||| ||||| |
8

||| ||||| |
9

||| ||||| |
Enter

Clear Data

Scan the following bar code to clear all batch bar code data on the scanner. This deletes the BarcodeFile.txt from the scanner.

Clear Data